U.S. Coast Guard (CG-3PSE-4) 2100 Second Street, S.W. Washington, DC 20593-0001 Phone: (202) 372-1392 FAX: (202) 372-1925 E-mail: Kurt.J.Heinz@uscg.mil www.uscg.mil/hq/q-/mse4/mse4/mse4/mse4/mse.htm

16714/161.011/Jotron March 26, 2008

Jotron AS P.O. Box 54 NO-3280 Tjodalyng, Norway

Subj: TRON 40S and 40GPS Mk II, CATEGORY 1 or 2, 406 MHZ EPIRB

Dear Mr. Storjordet,

This is in response to your letter dated January 31, 2008, requesting approval of the modifications to the Jotron Tron 40S and Tron 40GPS EPIRBs (modified versions denoted with Mk II suffix). Based on the information and test results provided, and in accordance with 47 CFR 80.1061 (c)(2), we conclude that the Tron 40S Mk II and 40GPS Mk II meet the relevant requirements of the Radio Technical Commission for Maritime Services (RTCM) recommended standards for 406 MHz satellite EPIRBs (version 2.1, RTCM paper 77-2002/SC110-STD).

The Tron 40S Mk II and 40GPS Mk II EPIRBs are COSPAS-SARSAT Class 2 (-20° C) units available with an automatic float-free bracket (RTCM Category 1) or manual release bracket (RTCM Category 2). Category 1 units may utilize either the McMurdo BreaktHRU or Hammar H2OE hydraulic release units (HRUs).

If you have any questions regarding this matter, please contact Lieutenant Commander Michael Simbulan of my office at (202)372-1356.

K. J. HEINZ

Chief, Lifesaving and Fire Safety Division

U.S. Coast Guard

By direction

Copy: FCC (EAB)

Federal Communications Commission

Authorization and Evaluation Division (EAB)

7435 Oakland Mills Road Columbia, MD 21406