




TECHNICAL BULLETIN TB04-2014

Regarding:

How to mount a new lanyard on Tron 40S/Tron 40GPS/
Tron40s mkII and Tron 40 GPS mkII



Please follow instructions in pictures below



Tjodalving, June, 20th 2014 /FIT

DNB Bank asa | 0021 Oslo | Norway | Bank account: 24400508514 | IBAN: NO6624400508514 | BIC: DNBANOKK | Reg.no.: NO917713324 MVA
QA Certificate: NS-EN ISO 9001:2008/ISO 14001:2004

www.jotron.com

Jotron AS
P.O. Box 54 | NO-3281 Tjodalving | Norway

Tel: +47 33 13 97 00
Fax: +47 33 12 67 80